

Technical Support Bulletin 2016-02

Best Practice Battery Connection

November 4, 2016

Alert Level: **IMPORTANT** Instruments: MMP, ITP Software Versions: 5.24 and lower Hardware Version: N/A

Subject: Best Practice Steps for Battery Connection and Re-initializing the Watchdog Alarm Clock

Summary: When you plug in the main battery, always connect to the profiler and interrupt the automatic 30 second initialization countdown.

Technical Details: When plugging in the main battery, always connect to the Profiler and interrupt the automatic 30 second initialization countdown. This 30 second countdown must be interrupted to re-initialize the watchdog alarm clock when the main battery has been disconnected from the electronics for some time. If the watchdog alarm clock is not re-initialized, it will reset every 68 minutes during the deployment, regardless of what has been programmed. A new Dive 0 occurs after every watchdog re-set. As a result, the Profiler will run significantly more, and will not correctly execute the programmed deployment.

Solution: As a Best Practice, every time you plug in the main battery, connect to the firmware with your computer using Motocross and interrupt the automatic 30 second initialization countdown to re-initialize the watchdog clock. Follow these steps:

- 1. Connect the main battery.
- 2. Connect your computer to the Profiler firmware with Motocross.



3. Press [CTRL]-[C] to interrupt the automatic 30 second countdown and re-initialize the watchdog clock.

```
D:PROFILER
```

CF2-MPP-5.00 R9 L2.0 U304 5 00.c compiled Jan 3 2013 at 00:50 S/N ML12345-67D Pattern Profiler © 1999-2013 McLane Research Laboratories. All rights reserved. The "Pattern Profiler" MPP operator interface is now running. Type ^C within 30 seconds to assert control and initialize system. 28 seconds [^C] Clock reads 01/03/13 12:42:04. Change it [N] ? y Enter date as mm/dd/yy or mm/dd/yyyy, time as hh:mm:ss Enter correct time [01/03/2013 12:42:13] ? 01/03/2013 12:42:32 Clock reads 01/03/13 12:42:32. Change it [N] ? SYSTEM Checking FlashCard ... done. 01/03/13 12:42:35 01/03/13 12:42:35 SYSTEM 35 files found on disk. SYSTEM Capture is disabled. SYSTEM D:CAPTUR*.TXT size is ~0.00 MB of 8.1 MB max. 01/03/13 12:42:36 01/03/13 12:42:36 01/03/13 12:42:36 SYSTEM Reading D:ODOMETER.DAT ... done. 01/03/13 12:42:36 SYSTEM History: 67.41 motor hours, 891 meters. 01/03/13 12:42:36 SYSTEM Hardware: Rev-D. Motor OpAmp offset: 31mA. 01/03/13 12:42:37 SYSTEM Watchdog initialized. 01/03/13 12:42:37 SYSTEM Watchdog alarm IRQ has been activated. 01/03/13 12:42:37 SYSTEM Setting watchdog clock ... done. 01/03/13 12:42:37 SYSTEM Loading URAO ... done. 01/03/13 12:42:37 SYSTEM Initializing sensors done. 01/03/13 12:42:37 SYSTEM Sizing CompactFlash ... done. 01/03/13 12:42:38 SYSTEM CompactFlash: 0.6 MB used, 986.6 MB free, 987.2 MB size. 01/03/13 12:42:38 SYSTEM Backup battery measures 3.2V. 01/03/13 12:42:38 SYSTEM Main battery measures 12.0V. 01/03/13 12:42:38 SYSTEM Loading schedule information ... 01/03/13 12:42:39 SYSTEM Loading SCHEDULE.DPL. 01/03/13 12:42:39 SYSTEM Scheduled dive zero time is 12/14/12 11:55:00. 01/03/13 12:42:39 SYSTEM Filling in schedule years ... done. 01/03/13 12:42:39 SYSTEM Loaded SCHEDULE.DPL. 01/03/13 12:42:39 SYSTEM Generating SCHEDULE.TXT ... done.

Figure 1: [CTRL]-[C] Interrupts the Automatic 30 Second Initialization Countdown

- 4. Optionally confirm the watchdog alarm clock has been reset by running the 2 second watchdog test in the Bench Test menu.
- 5. Disconnect your computer, seal the controller housing, and deploy the Profiler.

Note - In the case of a true unattended reset, the power is temporarily removed and a watchdog alarm clock reinitialization is not required. This is the case when the firmware is operating unattended during a deployment.

A fix in firmware v5.25 provides an automatic re-initialization. However, it is still highly recommend that you connect to the profiler and interrupt the automatic 30 second initialization countdown whenever plugging the battery into the electronics.

Page 2 of 2

Tel: +1 508 495 4000