McLANE RESEARCH LABORATORIES, INC.

Deployment Planner Release Note	Release v2.08	May 30, 2019

Summary of Deployment Planner Release v2.08: Deployment Planner Release v2.08 contains the following changes.

I. New functionality	Added a 'Check for Updates' feature to upgrade from Deployment Planner Release v2.06 to Deployment Planner Release v2.08.
II. Enhanced functionality	Added the ability to start a terminal emulation session from within Deployment Planner.
III. General update	Changed the automatic numbering of the first profile within a Pattern to #1 to reduce confusion.
IV. General update	Updated the FSI ACM names in the Instrument Configuration sensor list to FSI ACM and ACM+.
V. General update	Changed profile duration options in the Profile Editor.

I. New functionality: Deployment Planner has a 'Check for Updates' feature on the File menu that was added in Release v2.06 and previously not documented. If this option is selected, the system prompts to upgrade to the current Deployment Planner version and installs the upgrade if prompted by the user. The most current Deployment Planner software can also be downloaded from the Profiler software menus on the McLane website.

Figure 1: Check for Deployment Planner Updates

Tel: +1 508 495 4000 www.mclanelabs.com Fax: +1 508 495 3333

II. Enhanced functionality: Deployment Planner Release v2.08 includes a new Terminal button that starts a terminal emulation session from within Deployment Planner. Terminal emulation can then be used to load a SCHEDULE.DPL file into the Profiler firmware.

Figure 2: Start a Terminal Emulation Session from Deployment Planner

Tel: +1 508 495 4000 **www.mclanelabs.com** **Fax: +1 508 495 3333**

III. General update: In Deployment Planner Release v2.08, the first profile within a pattern is now #1 rather than #0, to reduce confusion with the default Pattern which is #0.

Figure 3: First Profile is #1

Tel: +1 508 495 4000 **www.mclanelabs.com** **Fax: +1 508 495 3333**

IV. General update: In Deployment Planner Release v2.08, the FSI ACM selection was re-labeled FSI ACM/ACM +.

Figure 4: FSI ACM Selection

Tel: +1 508 495 4000 **www.mclanelabs.com** **Fax: +1 508 495 3333**

V. General update: In Release v2.08, the 'Same as Total Dive Time' checkbox was removed. To program consecutive (back to back) profiles, use the checkbox 'Start the Next Profile Immediately following This Profile'. If creating back to back profiles, you can optionally use 'Set Specific Duration', to define a time between the start of the profiles, or leave 'Set Specific Duration' blank for an immediate start.

Figure 5: Profile Duration

Tel: +1 508 495 4000 **www.mclanelabs.com** **Fax: +1 508 495 3333**