

Technical Support Bulletin 2003-04	3-pin Comm Cable	Oct 15, 2003
---	-------------------------	---------------------

Alert Level: **INFORMATIONAL**
 Software Version: N/A
 Instrument: All Controllers with 3-pin COM Connector
 Subject: COM cable wiring

Summary: The cable connecting the controller to the PC must be wired correctly for proper communications.

Potential Negative Effects: Incorrect wiring will result in no response from the controller

Technical Details: The wiring diagram for the Impulse RMG-3-FS to DB-9 is shown below. The pin numbering found in the Impulse documentation is also shown for the mating bulkhead connector. There are no pin numbers printed on the connector itself.

